

# **TEST CERTIFICATE**

This document certifies that

V1238 O-rings from

# Seal Group, Parker Hannifin Corporation

passed the requirements of

# NORSOK M710 in respect of rapid gas decompression resistance in 3% carbon dioxide at 150 bar and 100°C

Test gas:
Test temperature:
Test pressure:
Decompression rate:
Passed by :
Date:

3% CO<sub>2</sub> balance methane 100°C 150 bar (15 MPa) 20 bar/minute G J Morgan (B Sc. Hons.) G.J. Morgan 20 bar/minute

MATERIALS ENGINEERING RESEARCH LABORATORY LTD

Wilbury Way, Hitchin, Hertfordshire, SG4 0TW, United Kingdom. T: +44 (0) 1462 427850 F: +44 (0) 1462 427851 enquiries@merl-ltd.co.uk www.merl-ltd.co.uk

MERL verify that O-rings manufactured by Seal Group, Parker Hannifin Corporation from their elastomer V1238 have been subjected to a multicycle series of rapid gas decompression tests under the conditions detailed below. After 10 cycles, no failures were seen in any of the four test O-rings. These results indicate that the V1238 elastomer can be realistically considered for use in the same or less severe conditions.

### Seal Conditions

O-ring details:-	Elastomer	V1238
	Size	BS 1806 size 312
	Section dimater	5.33mm
	Internal diameter	15.24mm

## Test Gas

3% CO<sub>2</sub> in methane

### **Procedure and Test Conditions**

For each test cycle the following procedure and conditions applied:

- 1) the assembly was heated to 100°C and this temperature maintained throughout
- 2) a pressure of 150 bar (15 MPa), using the test gas, was applied
- 3) this pressure was maintained for 72 hours minimum initially
- 4) a rapid decompression in 7.5 minutes from 150 bar to ambient was performed
- 5) ambient pressure was maintained for one hour and pressure cycled every 24 hours

After 10 cycles, each O-ring was quartered, inspected and observations recorded.

### **Observations**

<u>O-ring</u>	Observations on test O-ring after test	
1	One crack across 75% of one cross section, no splits	
	cracks, blisters or unevenness in other three sections	
2	One crack across 10% of one cross section, no splits	
	cracks, blisters or unevenness in other three sections	
3	No splits cracks, blisters or unevenness in any sections	
4	No splits cracks, blisters or unevenness in any sections	

### **Summary**

For four V1238 O-rings tested, no elastomer failures occurred after 10 rapid gas decompression cycles made under the conditions described above.

